

Community Complaints Summary

BHP Mt Arthur Coal Community Response Line: 1800 882 044

February 2019

| Date and time | From | Issue | Lodgement type | Investigation and response to caller |
|---------------------|---------------------------------------|-------------------|-------------------------|---|
| 03/02/2019 | Roxburgh Road | Operational Noise | Community Response Line | Investigation revealed no unusual mining operations were occurring at the time. Results at the nearest real-time monitor were un available due to monitor being non-operational. |
| 04/02/2019 17:46 | Racecourse Road/Sheppard Avenue | General Dust | Community Response Line | Investigation revealed mining operations had already ceased at the time. Results at the nearest monitor indicated dust levels were not elevated at the time, and the 24 hour average remained within regulatory criteria. Caller was advised of investigation and monitoring results. |

| 04/02/2019 17:49 | Racecourse Road/Sheppard Avenue | General Dust | Community Response Line | Investigation revealed mining operations had already ceased at the time. Results at the nearest monitor indicated dust levels were not elevated at the time, and the 24 hour average remained within regulatory criteria. Caller was advised of investigation and monitoring results. |
|---------------------|---------------------------------------|-------------------|-------------------------|---|
| 06/02/2019 | Roxburgh Road | Operational Noise | Community Response Line | Investigation revealed no unusual mining operations were occurring at the time. |
| 4:48 | | | | Results at the nearest real-time monitor were un available due to monitor being non-operational. |
| 08/02/2019 | Denman Road | Blast Vibration | Community Response Line | Investigation revealed weather conditions were suitable for blasting at the time. Results |
| 11:33 | | | | indicated overpressure noise and ground vibration levels were within regulatory criteria. |
| 08/02/2019 | Denman Road | Blast Vibration | Community Response Line | Investigation revealed weather conditions were suitable for blasting at the time. Results |
| 12:00 | | | | indicated overpressure noise and ground vibration levels were within regulatory criteria. |
| 11/02/2019 | Roxburgh Road | Operational Noise | Community Response Line | Investigation revealed no unusual mining operations were occurring at the time. |
| 22:28 | | | | Results at the nearest real-time monitor were un available due to monitor being non-operational. |

| 15/02/2019 | Muswellbrook | General Dust | Community Response Line | Investigation revealed mining operations had already ceased at the time. Results at the |
|---------------------|---------------|-------------------|-------------------------|--|
| 12:58 | | | | nearest monitor indicated dust levels were not elevated at the time, and the 24 hour average remained within regulatory criteria. Caller was advised of investigation and monitoring results. |
| 20/02/2019 | Roxburgh Road | Operational Noise | Community Response Line | Investigation revealed no unusual mining |
| 11:45 | | | | operations were occurring at the time. Results at the nearest real-time monitor indicated noise levels were within regulatory criteria. |
| 21/02/2019 10:56 | Muswellbrook | Blast Dust | Community Response Line | Investigation revealed weather conditions were suitable for blasting at the time. Results at the nearest monitor indicated dust levels were not elevated at the time, and the 24 hour average remained within regulatory criteria. Caller was advised of investigation and monitoring results. |
| 28/02/2019 | Roxburgh Road | Operational Noise | Community Response Line | Investigation revealed no unusual mining operations were occurring at the time. |
| 1:05 | | | | Results at the nearest real-time monitor indicated noise levels were within internal benchmarks. |