

Goonyella Riverside to South Walker Creek Mine Dragline Move – EPBC 2016/7788 Compliance Report 20 June 2017 – 19 June 2018

16 October 2018



Contents

Introduction	1
Description of activities	2
Compliance Table	3

Introduction

The Project involves the relocation of a dragline, along a 77km route, from Goonyella Riverside Mine to South Walker Creek Mine, Queensland. The Project dragline move route is located near Moranbah, Nebo and Coppabella within the Isaac Regional Council Local Government Area of Queensland.

BMC sought a federal approval under the *Environmental Protection and Biodiversity Conservation Act 1999* (*EPBC Act*) for potential impact on Matters of National Environmental Significance (MNES) due to 'the dragline relocation'. This approval was granted on 2 May 2017. Construction in the approval area commenced on 20 June 2017.

The following report addresses compliance with all conditions in accordance with condition 14 of the *EPBC Act* approval (Approval Reference EPBC2016-7788):

"Within three months of every 12 month anniversary following commencement of the action, the approval holder must publish a report on their website addressing compliance with each of the conditions of this approval, including implementation of the Offset Management Plan and Rehabilitation Management Plan as specified in the conditions. The approval holder must provide the Department with evidence of publication on the same day the report is published. Reports must remain published for the life of the approval. The approval holder must continue to meet the requirements of this condition until such time as agreed to in writing by the Minister."

Description of activities

EPBC Number	2016/7788
Project Name	Goonyella Riverside Mine to South Walker Creek Mine Dragline Move, QLD
Approval Holder and ABN	BHP Billiton Mitsui Coal Limited ABN: 34 009 713 875
Approved Action	Relocate a dragline, along a 77km route, from Goonyella Riverside Mine to South Walker Creek Mine, Queensland [See EPBC Act referral 2016/7788].
Location of the Project	Near Moranbah, Nebo and Coppabella within the Isaac Regional Council Local Government Area of Queensland, between the Goonyella Riverside Mine and the South Walker Creek Mine.
Person accepting responsibility for the report	Edward Nock
Date of Preparation	16 October 2018

Compliance Table

In accordance with condition 14 of the *EPBC Act* approval (Approval Reference EPBC2016-7788), this report provides an update of SWC's compliance against the relevant approval conditions (Table 1).

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move – Compliance Report

Condition Number	Condition		Compliant/ Non Compliant/ Not Applicable	Evidence/Comn	nents		
1	1. Prior to any clearing a spotter/catcher must under fauna survey to identify list that may inhabit the area: The survey must: i. identify and flag all hollo potential breeding sites wand where possible search fauna; ii. involve a search of likel includes rocky areas, falle woody debris, gullies and iii. if fauna is present and fauna spotter/catcher must a near-by habitat that is not clearing.	ertake a pre- clearance sted threatened species ow bearing trees and ithin the clearing area h hollows for resident by ground habitats that en logs, burrows and banks; and can be relocated the st relocate the fauna to	Compliant	Vulnerable and N Ecological Const 2016. Targeted surveys Environmental S Spotter-Catcher Locations of pote and flagged. The locations of recorded via han The surveys also Fauna Spotter-C were present dur	surveys to determine the Near Threatened fauna is cultants during 18-22 Augustants during 18-22 Augustants during 18-22 Augustants during 18-22 Augustants during and ignificance (MNES) were from BAAM Ecological Cential animal breeding and any observations of cond-held GPS. In involved searches of gratchers from the Queen atchers from the Queen ing clearing activities were flagged during the	species were undertake gust 2016 and 29 Augu d sheltering places for le undertaken by an Ec Consultants from 21 – 2 and sheltering place feat asservation significant special round habitats.	en by from BAAM st – 2 September Matters of National ologist and Fauna 26 February 2017. tures were recorded becies were
2	The approval holder must not exceed the disturbance limits detailed in Table 1 within the project area.		disturbance limits detailed in Table 1 within the	Protected Matter	Disturbance Limits (hectares)	Actual Cleared (includes Core, Essential, General)	Variance
	Table 1 Protected Matter	Disturbance Limits (hectares)		Ornamental snake	52.44	35.84	-5.96

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move - Compliance Report

Condition Number	Condition	Condition Compliant/ Non Compliant/ Not Applicable		Evidence/Comments			
	Ornamental snake	52.44		Yakka snake	105.63	48.52	-34.68
	Yakka snake	105.63		Brigalow	9.73	3.74	-50.93
	Brigalow	9.73					
3			Compliant			.210 – Isaac Regional C ment of Natural Resourd	
4	Within 6 months of the commencement of the action the approval holder must provide written evidence to the Department demonstrating the actions that have been and will be taken to legally secure the offset area(s).		Compliant	An email dated 4 August 2017 was submitted from BHP to the Department of Environment and Energy at 3:11pm. The email provided confirmation that the area has now been legally secured as required by the approval and included copy of the Voluntary Declaration Notice (VDN) under subsection 19E – 19L Vegetation Management Act 1999. The VDN was signed by the Acting Senior			mation that the offset al and included a ion 19E – 19L of the
	Protected Matter	Habitat area (hectares)		Department of Natu	ıral Resources and	r of the Central Region, Mines on 24 July 2017.	The email also
	Ornamental snake	254.6		included the GIS sh	napenie for the Croy	don Station Offset Area	l .
	Yakka snake	245.8					
	Brigalow	113.7					
5	Within 3 months of legal area(s) the approval hol Department in writing of offset area(s) were legal the Department with the	der must advise the the actual date the lly secured and provide	Compliant	Refer to evidence fr	rom Condition 4.		

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move – Compliance Report

Condition Number	Condition			Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
6	i. from the date secured and the the approval ho reduction in half	older must achie e offset area(s): the offset area(s en on for the life lder must ensure oitat quality of the the habitat quali) are legally of the approval, there is no endinger offset area(s)	Compliant	Inspection undertaken in April 2018 indicated no reduction in habitat quality of the offset area as compared to Table 3.
	Protected Matter Ornamental snake Yakka skink Brigalow ii. within 5 years	Habitat quality for remnant vegetation 7 7 7 6 of legally secur	Habitat quality for regrowth vegetation 6 5 6		
	area(s) the app	roval holder mus	Habitat quality for regrowth vegetation 6 5		

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move – Compliance Report

dition ber	Condition			Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
	area(s) the app	roval holder mu	curing the offset est ensure that the quality detailed in		
	Protected matter	Habitat quality for remnant vegetation	Habitat quality for regrowth vegetation		
	Ornamental snake	8	6		
	Yakka skink	7	6		
	Brigalow	7	6		
	area(s) the app	roval holder muneet the habitat	curing the offset est ensure that the quality detailed in		
	Protected	Habitat quality for remnant	Habitat quality for regrowth		
	matter	vegetation	vegetation		
	Matter Ornamental snake	vegetation 8	vegetation 7		
	Ornamental	 			

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move – Compliance Report

Condition Number	Condition	Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
7	The approval holder must implement the Rehabilitation Management Plan within 12 months of the commencement of the action. i. the approval holder may choose to revise and improve elements of the Rehabilitation Management Plan if the revised elements of the Rehabilitation Management Plan are unlikely to cause a new or increased impact. ii. prior to the implementation of the Rehabilitation Management Plan the approval holder must publish the Rehabilitation Management Plan must remain on the website for the life of the approval. iii. within 14 calendar days of any revised Rehabilitation Management Plan by the approval holder, the approval holder must advise the Department in writing of the actual date the Rehabilitation Management Plan was revised.	Compliant	Rehabilitation work was completed prior to the 2017/2018 wet season. (i) No revisions of the Rehabilitation Management Plan have been made. (ii) The July 2017 BMC Dragline Move Rehabilitation Management Plan is on BHP's Regulatory Website (https://www.bhp.com/environment/regulatory-information). It was uploaded on 21 July 2017. (iii) No revisions of the Rehabilitation Management Plan have been made.
8	Prior to legally securing the offset area(s), the approval holder must have an offset management plan for the offset area(s) in place. The offset management plan must: i. be designed so that the results are adequate to inform adaptive management and demonstrate that the outcomes under condition 6 of this approval are on-track to be achieved (before they are due) and have been achieved (at the time they are due)	Compliant	An Offset Area Management Plan Croydon Station was prepared in January 2017. The Offset Area Management Plan was reviewed by the DOEE. The Croydon Station offset area was secured in July 2017.

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move – Compliance Report

Condition Number	Condition	Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
	ii. include contingency measures to mitigate the risks of not achieving the outcomes under condition 6 of this approval		
	iii. include written evidence and review from an ecologist		
	iv. take account of the Ornamental Snake conservation advice, the Yakka Skink conservation advice, and the Brigalow conservation advice.		
9	The approval holder must publish the Offset Management Plan prior to legally securing the offset area(s) and the Offset Management Plan (and any subsequent revised versions) must remain on the website for the life of the approval. The results of the Offset Management Plan must be included in the annual compliance report required under condition 14 of this approval.	Compliant	An Offset Area Management Plan Croydon Station was prepared in January 2017. The Croydon Station offset area was secured in July 2017. The Offset Area Management Plan was uploaded onto the BHP Regulatory website on 26 July 2017 and will remain on the website for the life of the approval. An inspection was undertaken on 24 April 2018 by Earthtrade. The offset was found to be compliant with the Offset Area Management Plan. At the time of the inspection, there was a high level of ground cover (circa 89%) across the offset site. There was some differentiation in the groundcover composition with areas under brigalow regrowth where the groundcover consisted predominantly of brigalow leaf litter and small amounts of native grasses. More open areas and areas under eucalypt regrowth had higher levels of grass cover and less leaf litter. Activities undertaken included the movement of 500 head of cattle off the offset in October and the grading of firebreaks during October 2017 and May 2018. No damage was recorded.

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move - Compliance Report

Condition Number	Condition	Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
			Earthtrade concluded that there are no issues with non–compliance with the management plan. There are no emerging risks or threats that are over and above those identified in the management plan, and have actions detailed against them for mitigation purposes.
10	If, at any time during the life of the approval, monitoring indicates that the outcomes under condition 6 of this approval are not on track to be achieved, the approval holder must report to the Department in writing within 1 month of the monitoring. The report must state the cause, the response measures (including timeframes for reporting the success of those measures to the Department) and the actions to prevent further occurrences.	Not applicable	Monitoring undertaken does not indicate that the outcomes under condition 6 of this approval are not on track to be achieved.
11	If the Minister is not satisfied that the outcomes under condition 6 of this approval are likely to be achieved, or is not satisfied there is sufficient evidence that the outcomes under condition 6 of this approval are likely to be achieved (on the basis of information provided in annual compliance reports and or audits under these conditions of approval), the Minister may (in writing) request the approval holder to submit a plan for the Minister's approval, to monitor, manage, avoid, mitigate, offset, record or report on, impacts to the Ornamental Snake and or the Yakka Skink and or Brigalow. i. The Minister may set a timeframe in which the plan must be submitted, and may designate that the plan must be prepared or reviewed by an ecologist (or another specified person).	Not applicable	The Minister has not informed the Company that it is not satisfied that the outcomes under condition 6 of this approval are likely to be achieved.

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move - Compliance Report

Condition Number	Condition	Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
	ii. If the Minister approves the plan in writing then the approval holder must implement that plan (or a revised version if approved in writing by the Minister).		
12	Within 14 calendar days following commencement of the action, the approval holder must advise the Department in writing of the actual date of commencement of the action.	Compliant	Construction commenced on 14 June 2017. A letter was sent to the Department of the Environment and Energy on 20 June 2017.
13	The approval holder must maintain accurate records substantiating all activities associated with or relevant to the conditions of approval, including measures taken to implement the Offset Management Plan and Rehabilitation Management Plan, and make them available upon request to the Department. Such records may be subject to audit by the Department or an independent auditor in accordance with section 458 of the EPBC Act, or used to verify compliance with the conditions of approval. Summaries of audits will be posted on the Department's website. The result of audits may also be publicised through the general media.	Compliant	Documents are held within BHP's document management system.

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move – Compliance Report

Condition Number	Condition	Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
14	Within three months of every 12 month anniversary following commencement of the action, the approval holder must publish a report on their website addressing compliance with each of the conditions of this approval, including implementation of the Offset Management Plan and Rehabilitation Management Plan as specified in the conditions. The approval holder must provide the Department with evidence of publication on the same day the report is published. Reports must remain published for the life of the approval. The approval holder must continue to meet the requirements of this condition until such time as agreed to in writing by the Minister.	Non compliant	The report was not published onto the website within 3 months of the 12 month anniversary following commencement of the action. The report will be onto the website before 19 October 2018.
15	The approval holder must report any potential or actual contravention of the conditions of this approval to the Department in writing within seven calendar days of the approval holder becoming aware of a contravention.	Compliant	The Department was informed of the non compliance with Condition 14 on 15 October 2018 at 2:38pm. A letter detailing the non compliance was sent on 16 October 2018. The non compliance was identified on 13 October 2018.
16	Upon the direction of the Minister, the approval holder must ensure that an independent audit of compliance with the conditions of approval is conducted and a report submitted to the Minister. The independent auditor must be approved by the Minister prior to the commencement of the audit. Audit criteria must be agreed to by the Minister and the audit report must address the criteria to the satisfaction of the Minister.	Not applicable	No request has been received from the Minister.

Table 1 Goonyella Riverside Mine to South Walker Creek Mine Dragline Move - Compliance Report

Condition Number	Condition	Compliant/ Non Compliant/ Not Applicable	Evidence/Comments
17	If, at any time after five years from the date of this approval, the approval holder has not substantially commenced the action, then the approval holder must not substantially commence the action without the written agreement of the Minister.	Compliant	The action commenced on 14 June 2017.

New environmental risks

No new environmental risks from the Project were identified during the reporting period.

Declaration of accuracy

In making this declaration, I am aware that sections 490 and 491 of the *Environment Protection and Biodiversity Conservation Act 1999* (Cth) (EPBC Act) make it an offence in certain circumstances to knowingly provide false or misleading information or documents. The offence is punishable on conviction by imprisonment or a fine, or both. I declare that all the information and documentation supporting this compliance report is true and correct in every particular. I am authorised to bind the approval holder to this declaration and that I have no knowledge of that authorisation being revoked at the time of making this declaration.

Signed:
Full name (please print): Edward Nock
Position (please print): HSE Superintendent
Organisation (please print including ABN/ACN if applicable): BHP Billiton Mitsui Coal Limited, ABN: 34 009 713 875
Date: 16 October 2018