

Date	Time	From	Issue	Lodgment Type	Investigation and Response to Caller
4/12/2025	11.30am	Denman Road	Blast Vibration	Community Response Line	Investigation confirmed that weather conditions were suitable for blasting at the time. Results indicated overpressure noise and ground vibration levels were within regulatory criteria. Caller was advised of investigation and monitoring results.
4/12/2025	11.30am	Roxburgh Road	Blast Vibration	Community Response Line	Investigation confirmed that weather conditions were suitable for blasting at the time. Results indicated overpressure noise and ground vibration levels were within regulatory criteria. Caller was advised of investigation and monitoring results.
4/12/2025	11.30am	Denman Road	Blast Vibration and Notification	Phone Call	Investigation confirmed that weather conditions were suitable for blasting at the time. Results indicated overpressure noise and ground vibration levels were within regulatory criteria. Caller was advised of investigation and monitoring results. A blast notification had not been sent due to an internal miscommunication. Caller was advised this was a single occurrence and plans have been put in place to improve process.
4/12/2025	11.30am	Denman Road	Blast Vibration and Notification	Phone Call	Investigation confirmed that weather conditions were suitable for blasting at the time. Results indicated overpressure noise and ground vibration levels were within regulatory criteria. Caller was advised of investigation and monitoring results. A blast notification had not been sent due to an internal miscommunication. Caller was advised this was a single occurrence and plans have been put in place to improve process.