



Community Complaints Summary

May 2017

04/05/2017 11.35pm	Roxburgh Rd	Light	Community Response Line	Clear light shining directly onto house. Investigation found that a light had been set up and at some stage and was shining towards Roxburgh road but was identified internally just before receiving the call from community member and the light was already repositioned so it wasn't facing Roxburgh Rd.
16/05/2017 12:07pm	Denman Rd	Blast	Community Response Line	Caller felt 3 blasts, saw some dust. Investigation revealed weather conditions were suitable for blasting at the time. Results indicated overpressure noise and ground vibration levels were within regulatory criteria and that dust created by blast remained on site. Caller was advised of investigation.
