


Zone of Influence

A minimum 1.0m clearance from the zone of influence is required for any plant, vehicle and storage of materials (including excavated materials or any other heavy loads)

NO WORKERS shall be within the trench when the plant is within the excavation's zone of influence. Plant or worker shall relocate.

Note:

A minimum of 1.0m clearance from the edge of the trench (shoring) can be adopted only if the ground support system installed has been designed by a competent person to carry such loads



i Document Reference - MAC-STE-PRO-026