

#### 4.8.15 Seatbelts, Seats, Windows and Headlights

Seatbelts shall be worn at all times when road going vehicles and heavy vehicles are in motion.

The only exception to this is the operation of drills where it may be necessary to stand up for increased visibility during tramming and drilling operations as determined by a 60 seconds for safety.

Windows on all vehicles and equipment should be up at all times to assist with the reduction of dust exposure.

Road going vehicles and all heavy equipment excluding excavators and drills must have headlights on at all times when operating with the exception of:

1. The first truck in queue at the coal hopper may turn its headlights off if it cannot position itself to avoid glare to a truck operator reversing into the hopper. In this circumstance, headlights can only be off while the vehicle is stationary and must be turned back on before moving.



*Document Reference - MAC-STE-MTP-027*